

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	27	"5645448"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/15 16:15
L2	78	fuse with transparent and battery	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/15 16:16
S1	0	fuse and view-enabling	USPAT	OR	OFF	2004/09/27 16:28
S2	461	fuse with transparent	USPAT	OR	OFF	2005/02/15 16:14
S3	68	fuse with transparent and "439"/\$	USPAT	OR	OFF	2004/09/27 16:29
S4	68	fuse with transparent and "439"/\$	USPAT	OR	OFF	2004/09/27 16:30
S5	47	fuse with transparent and battery	USPAT	OR	OFF	2005/02/15 16:16
S6	2482	fuse with battery	USPAT	OR	OFF	2004/09/27 16:36
S7	24	fuse with battery with casing	USPAT	OR	OFF	2004/09/27 16:36
S8	1	"6294978".PN.	USPAT	OR	OFF	2004/09/27 16:37
S9	1	"5886611".PN.	USPAT	OR	OFF	2004/09/27 16:38
S10	1	"5877609".PN.	USPAT	OR	OFF	2004/09/27 16:38
S11	1	"5748068".PN.	USPAT	OR	OFF	2004/09/27 16:39
S12	1	"5643693".PN.	USPAT	OR	OFF	2004/09/27 16:40
S13	1	"5034620".PN.	USPAT	OR	OFF	2004/09/27 16:43
S14	13	"5034620"	USPAT	OR	OFF	2004/09/27 17:03
S15	1	"4798968".PN.	USPAT	OR	OFF	2004/09/27 17:11
S16	1	"4581504".PN.	USPAT	OR	OFF	2004/09/27 17:12
S17	1	"3410359".PN.	USPAT	OR	OFF	2004/09/27 17:12
S18	22	"5645448"	USPAT	OR	OFF	2005/02/15 16:15